

Oil Field Environmental Incident Summary

Incident: 20141110182017 **Date/Time of Notice:** 11/10/2014 18:20

Responsible Party: HRC Operating, LLC.

Well Operator: HRC OPERATING, LLC

Well Name: RASMUSSEN 1-21-16H

Field Name: STRANDAHN

Well File #: 20844

Date Incident: 11/9/2014 **Time Incident:** 15:45

Facility ID Number:

County: WILLIAMS

Twp: 157

Rng: 102

Sec: 21

Qtr: SW SE

Location Description: 10'x20' area adjacent to flare scorched and oil impacted

Submitted By: Kelly Grimm

Received By:

Contact Person: Chris Martinez
1801 California St
Suite 3500
Denver, CO 80202

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	Gallons	5	Gallons	5	gallons

Brine

Other

Description of Other Released Contaminant:

NA

Inspected:

Written Report Received: 11/27/2015

Clean Up Concluded: 11/15/2014

Risk Evaluation:

No immediate health hazards.

Areal Extent:

20'x10' area impacted. A self-extinguishing fire affected a 5'x10'.

Potential Environmental Impacts:

Primary impacts to vegetation.

Action Taken or Planned:

Use caution when bleeding down well and watch for signs of pressure fluctuations

Wastes Disposal Location: E&P approved disposal

Agencies Involved:

Updates

Date: 11/13/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to unspecified cause (suspect a treater upset), ejected burning oil through the flare stack. Some sprayed off location. Followup is necessary to determine extent and ensure cleanup.

Date: 11/19/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

11/19/14 - 13:00 on location. Release as described in report. Scorched area on the south side of the flare area. No oil residual remaining. Scorch is approximately 30 feet beyond the side of the pad and on to a grassed area in the 75 feet between the pad and the township road. No further inspection necessary.